
MURRAY BRIDGE AVEAX CODE 5019

FULL NOTAM SERVICE NOT AVBL



SA UTC +9:30 YMBD 350400S 1391336E VAR 8 DEG E UNCR

AD OPR Comak Pty Ltd, PO Box 88, Aldgate, SA, 5154. Email: bantel@internode.on.net. PH 0408 841 066.

REMARKS

- 1. PPR AD HR: 2330-0700 UTC.
 - After AD HR Some lighting AVBL. Contact ARO.

HANDLING SERVICES AND FACILITIES

H24 PN. Fuel by prior arrangement outside AD HR - Phone 0422 755 831.

METEOROLOGICAL INFORMATION PROVIDED

2.

METAR/SPECI.

PHYSICAL CHARACTERISTICS

RWY 01/19 gravel 1,065M.

RWY 09/27 grass 910M with 2% upward slope to W.

ATS COMMUNICATIONS FACILITIES

FIA ADELAIDE CENTRE 130.45 Circuit Area

LOCAL TRAFFIC REGULATIONS

- 1. ACFT taking off RWY 27 are not visible from THR RWY 19.
- Northern hold point/exit along RWY 01/19 referred to as "Alpha" and Southern hold point/ exit referred to as "Brayo".

FLIGHT PROCEDURES

No straight-in approaches when other circuit traffic.

CTAF 127.5

ADDITIONAL INFORMATION

- PJE 3NM NW.
- Glider OPS at AD.
- CAUTION: Blasting 1030-1500 Local at Kanmantoo Mine 11NM west of AD.
- 4. D285 applies to this area. Assume the Aerobatic Box is active and exercise caution.
- Aerobatic Box to E of and adjacent RWY 01/19 SFC-4000 1,000M x 1,000M. Use of the Aerobatic Box requires prior approval FM the OPR. The Aerobatic Box will be ACT by radio FREQ CTAF 127.50 for periods up to 20MIN only. During activation of the Aerobatic Box no crosswind joins will be permitted and RWY 09/27 will not be available.

CHARTS RELATED TO THE AERODROME

WAC 3458.